

Lead in Water Testing Results  
South Washington County Schools  
Pullman Elementary

On December 28<sup>th</sup>, 2018 Pullman Elementary School's drinking water was tested for concentration of lead.

**All water sources tested less than 20 parts-per-billion.**

**No action was taken at this time.**

<b>LOCATION</b>	<b>SOURCE</b>	<b>RESULTS (in ug/L)</b>
Nurse's Office	SINK	7.1
Staff Lounge	SINK	3.3
Hallway (outside gym)	FOUNTAIN	2.0
Cafeteria	FOUNTAIN	0
Cafeteria	BOTTLE FILLER	0
Kitchen	SINK	3.2
Kitchen	SPRAYER	5.3
Media Center Workroom	SINK	9.4
Room 101	SINK	11.5
Room 101	FOUNTAIN	3.1
Room 102	SINK	8.9
Room 102	FOUNTAIN	2.3
Room 103	SINK	11.0
Room 103	FOUNTAIN	3.1
Room 104	SINK	11.9
Room 104	FOUNTAIN	4.3

Room 105	SINK	15.8
Room 105	FOUNTAIN	3.4
Room 106	SINK	4.2
Room 106	FOUNTAIN	3.2
Hallway (outside 106)	FOUNTAIN	9.0
Room 107	SINK	10.0
Room 107	FOUNTAIN	1.8
Room 108	SINK	8.5
Room 108	FOUNTAIN	4.2
Room 109	SINK	11.6
Room 109	FOUNTAIN	2.5
Room 110	SINK	8.9
Room 110	FOUNTAIN	5.1
Room 111	SINK	9.8
Room 111	FOUNTAIN	3.4
Room 112	SINK	10.9
Room 112	FOUNTAIN	5.4
Room 113	SINK	8.7
Room 113	FOUNTAIN	4.1
Room 114	SINK	8.9
Room 114	FOUNTAIN	5.4
Room 115	SINK	6.8
Room 115	FOUNTAIN	5.7
Room 116	SINK	5.8
Room 116	FOUNTAIN	4.5

Room 117	SINK	4.6
Room 117	FOUNTAIN	9.3
Room 118	SINK	10.7
Room 118	FOUNTAIN	12.8
Room 119	SINK	10.3
Room 119	FOUNTAIN	5.2
Room 120	SINK	5.0
Room 120	FOUNTAIN	4.8
Room 121	SINK	8.1
Room 121	FOUNTAIN	5.8
Room 122	SINK	4.4
Room 122	FOUNTAIN	4.4
Room 123	SINK	3.3
Room 123	FOUNTAIN	3.7
Room 124	SINK	4.5
Room 124	FOUNTAIN	5.4
Room KA	SINK	7.3
Room KA	FOUNTAIN	3.2
Room KB	SINK	8.9
Room KB	FOUNTAIN	2.2